

Limonero 13

SERVICE PERFORMED**Filter Cleaning****TECHNICIAN****na Garcia****DURATION****2m****COMPANY****Limonero 13**

VIA SUMMARY

The filter system was cleaned and the equipment inspected. The salt cell plates were cleaned and scale removed, O-rings and seals were inspected, and the system was reassembled and tested. The control panel error code E2 was cleared during cleaning and now displays 6.9, and pump operation was verified.

VISIT NOTE

Cleaned salt cell plates and removed scale. Inspected O-rings and seals. Reassembled cell and tested system. Control panel error E2 cleared after cleaning, now displaying 6.9. Pump operation verified.

SERVICE CHECKLIST

- Cleaned filter cartridges/grids
- Inspected O-rings and seals
- Reassembled and tested
- Checked pump operation

DETAILS

CONDITION NOTES

Salt cell cleaned, scale removed. O-rings inspected.

PHOTOS (9)



